

February 26, 2002

SERVICE BULLETIN

Issue: Games with the XL to MAXX and Infinity to MAXX kits installed may experience rebooting and locking up.

Games Affected: Only the XL to MAXX and Infinity to MAXX kits that were built prior to February 5, 2002 are affected. No MAXX or FORCE games are affected.

Symptoms: Games can experience lock-ups and reboots.

Cause: There is a compatibility issue with the Unicom motherboard and the supplied memory DIMM strips.

Solution: The memory on the motherboard must be replaced. Enclosed you will find a replacement DIMM strip with part number SB0344-01 on the label.

RETURN the old DIMM strip to American Vending Sales for credit. If it is not returned, you will be charged \$95.00 per strip.

Questions?

Contact our Logic Department at 847.439.9400